

# 90/OFFER/2021







Producer	Mercedes Benz - VAN
Model	519 CDI 190 KM
Specification	Stock vehicle
Transmission	Automatic
External lights	Original LED Performence - Front - Rear
VIN	Sprinter
Number of passengers	22+1+1

Selected equipment

# **BODY WORK**

- Extension Back extension 50
- Roof Roof hatch Manual
- Windows
- Side High panoramic double
- Front Original
- Doors Electric Front
- Bumper

- Front Cuby Sport Panamerica
- Back Rear Original
- Seats mounting Floor wall
- Trunks Rear Deepened with preparation for the hook
- Seat platforms Full

#### PAINTING

• Colour: graphite metallic

Front painting

#### **ROOF AIR-CONDITIONING**

• Distribution - In shelves

#### SHELVES

- Standard With A/C chanel
- Service sets: vent, light, speaker
- Colour Beige
- Material between service sets Black

## UPHOLSTERY


- Colour Beige
- Ceiling Galaxy
- Sides
- Material Eco- leather
- Colour Black
- Structure Quilted
- Dashboard Covered in leather
- · Covering: anti-slip wood imitation

### ELECTRICAL AND ASSEMBLY

- Lighting
- Ceiling
- Pillars
- Above and under windows
- Seat platforms
- Audio
- Radio 2 Din
- TV
  - Type Manual
  - Quantity 2x
  - Size 17'
- Microphone
- Heating Convector heating
- Seats
- Scheme (Attachment 1)
- Features of the seat
  - Newspaper net

- Table
- Handles
- Armrest
- Side sliding
- PET
- Safety belts 3 pointed
- Quilted
- Backrest Adjustable
- Additional equipment
- Chrome hubcaps
- Chrome handles
- Chrome plate lighting strip
- Chrome finishing around the windows
  - Up
  - Down
- Carpets
  - Corridor
  - Under the seats
  - Entrance steps
- USB port Quantity and place for each seat row
- Camera Rear
- Marker lamps Roofing standard 4 pieces
- Fridges
- Towing hook

Attachments



Attachment 1 - Seats - Scheme