

# 230/SPECIFICATION/2022







Producer	Mercedes Benz - VAN
Model	519 CDI 190 KM
Specification	Stock vehicle
Transmission	Automatic
External lights	Original LED Performence - Front - Rear
VIN	Sprinter No. 491
Number of passengers	22+1+1
Customer name	STRONA INTERNETOWA
Delivery date	16.05.2022

## Selected equipment

### **BODY WORK**

- Extension Back extension 50
- Roof Roof hatch
- Windows
- Side Fake panoramic double
- Front Original

- Doors
- Front Electric
- Rear Original with glasses
- · Lifting Auto Cuby Bodykit
- Bumper Back Rear Cuby Sport
- Seats mounting
- Floor wall
- Cut the pillars for seats backrests
- Trunks Rear Deepened with preparation for the hook
- Floor Full

#### **PAINTING**

- · Colour Black (MB 197)
- · Additional varnished elements: laths and bumpers

#### **ROOF AIR-CONDITIONING**

• Distribution - In shelves

#### **SHELVES**

- Wave model
- · Service sets: vent, light, speaker
- Colour Beige
- Material between service sets Black

#### **UPHOLSTERY**

- Colour Beige
- · Ceiling Galaxy
- Sides
- Material Soft / textile
- Colour Black
- Structure Plain
- Dashboard
- Covering: wood imitation
- · Laths under and above the windows: black carbon
- Curtains

### **ELECTRICAL AND ASSEMBLY**


- Lighting
- Ceiling LED standard
- Above and under windows LED standard Colour blue
- Seat platforms LED standard
- Entrance step Logo
- Audio
- Radio 2 Din
- TV
  - Type Manual
  - Quantity 2x

- Size 19"
- Microphone
- Heating Convector heating VEHTEC
- Seats
- Scheme (Attachment 1)
- Features of the seat
  - Newspaper net
  - Table
  - Handles
  - Armrest Covered
  - Side sliding
  - LOGO
  - PET
  - Safety belts 3 pointed
  - Quilted
- Backrest Adjustable
- Legs Standard
- Additional equipment
- Chrome hubcaps
- Chrome mirrors
- Chrome plate lighting strip
- Carpets
  - Corridor
  - Entrance steps
- Converter in the platform
- 12V ports Quantity and place 2x front and rear
- USB port Quantity and place for each row of seats
- Camera Rear
- Marker lamps Roofing standard 4 pieces
- Fridges In place of the clipboard
- Wall behind driver Lack of table
- Railings
- Towing hook
- Other additional equipment: compartment for the driver in the shelf and on the trunk side

#### **GVW**

• 5300 kg

## Attachments



Attachment 1 - Seats - Scheme